



INSPECTION ANALYSIS



PASS

Vehicle Information	
Year	2015
Make	Lexus
Model	RX350

T.I.C.S. COSMETIC SCORE	T.I.C.S. STRUCTURAL SCORE	T.I.C.S. ANALYSIS CERTIFIED
98	98	

98

98



No Current Structural Damage


Inspection Information	
Mileage	27049
Date	03/10/18
Location	Sample, Florida
Inspector	Scott Foley
Order Number	451887

Vehicle Type
4 Door SUV



Cosmetic	Analytics
Front Bumper Cover	Repaired
Rear Bumper Cover	Original
Hood	Original
Cladding	N/A
Trunk/Hatch/Tailgate	Original
Right Fender	Original
Right Front Door	Original
Right Rear Door	Original
Right Cosmetic Rocker	Original
Right Cab Corner	N/A
Right Quarter Panel	Original
Right Bedside	N/A
Right Roof Rail	Original
Roof	Original
Left Fender	Original
Left Front Door	Original
Left Rear Door	Original
Left Cosmetic Rocker	Original
Left Cab Corner	N/A
Left Quarter Panel	Original
Left Bedside	N/A
Left Roof Rail	Original

*If any, Repairs will be noted on vehicle with RED indicator.



Structural	Body	
Left Quarter Panel		Pass
Right Quarter Panel		Pass
Roof		Pass
Left A Pillar		Pass
Left B Pillar		Pass
Left C Pillar		Pass
Left D Pillar		Pass
Right A Pillar		Pass
Right B Pillar		Pass
Right C Pillar		Pass
Right D Pillar		Pass
Left Rocker		Pass
Right Rocker		Pass
Left Rear Strut Tower		Pass
Rear Body Panel		Pass

Underhood	Structural	
Cross Member		Pass
Core Support		Pass
Firewall		Pass
Left Apron		Pass
Right Apron		Pass
Left Frame Rail		Pass
Right Frame Rail		Pass

Special Notes:



OBD2 Diagnostic - CLEAR



No Check Engine Lights

Each Transparency Inspection is performed by a trained technician using the latest in technology and industry experience. This report is limited to the vehicle's condition on the date the inspection was completed. This is not a warranty, or guarantee, when/in unreachable components or work done after inspection.

2015 Lexus RX 350



Mileage:	45,032	mode	
MPG:	18/25 (City/Hwy)	Int. Color:	Black/Cabernet
Drivetrain:	Front Wheel Drive	Stock #:	10052A
Ext. Color:	Claret Mica	Fuel Type:	Gasoline
Trans:	6-Spd Sequential Shift Auto (ECT-I) -inc: multi-mode and snow	VIN:	2T2ZK1BA3FC182669
		Engine:	6 Cylinders

Vehicle Location

Map

Fuccillo Nissan Orange Park
7447 Blanding Boulevard
Jacksonville, FL 32244

Call Us

904-269-9400



Save



Share



Tweet



Calculator



Transparency Inspection
\$200 VALUE FREE!
Cosmetic & Structural
Report

STICKER



We place these stickers on the inside of every car inspected. It shows the customer that you have paid for this car to be inspected.

The sticker also acts as a reminder to sales associates that there is an issue in a vehicle history report.



Highlights & Benefits of Transparency Inspections:

- Create transparency to the Consumer
- Inspections are live and to the Dealer within minutes
- Convert internet shopper to buyers
- Reports proven to help with any consumer “push back”
- Gives a sense of security to the Consumer
- Free demos for Sales and BDC Departments
- Analytics help given to show dealership the increased time spent on Vehicle Display page



CERTIFICATE OF ANALYSIS

Integrity of inspection, Excellence, experience

2015 Lexus RX 350
2T2ZK1BA3FC182669

Each Transparency Inspection is performed by a trained technician using the latest in technology experience.

SEPTEMBER 25, 2019

CHIEF INSPECTION OFFICER

